



21' Nautique SV 211 Team Ski and Wakeboard Boats

Location: Lewisville TX

**This is a Previously Listed Vessel
and is no longer offered for sale
on MarineSource**

**It is displayed for research and
informational purposes**

**If you would like assistance
locating a similar vessel**

[Click Here](#)

**to contact the MS member
about a similar listing**

Listing Number: PY-312008

Price: Was Listed At: \$ 42,800

Broker: POP Yachts
5717 Bessie Drive
Sarasota, FL
(941) 538-7803

LOA: 21'

Beam (ft): 7.58'

Model Year: 2005

Model Name: SV 211 Team

Hull Material: Fiberglass

Displacement: 3830 pound lbs.

Fuel Tank Capacity (gal): 38 gallons

Water Tank Capacity (gal): 0 gallons

Engine Horsepower (hp): 330 hp

No. of Engines: 1

Stock #312008 -

We are looking for people all over the country who share our love for boats. If you have a passion for our product and like the idea of working from home, please visit [WhereFreedomTakesYou \[dot\] com](http://WhereFreedomTakesYou.com) to learn more.

Please submit any and ALL offers - your offer may be accepted! Submit your offer today!

Reason for selling is no longer needing.

At Pop Yachts, we will always provide you with a TRUE representation of every vessel we market. We encourage all buyers to schedule a survey for an independent analysis. Any offer to purchase is ALWAYS subject to satisfactory survey results.

You have questions? We have answers. Call us at (941) 538-7803 to discuss this boat.

Selling your boat has never been easier. At Pop Yachts, we literally sell thousands of units every year all over the country. Call (855) 218-2805 and we'll get started selling your boat today.

Take a look at ALL *142 PICTURES*** of this vessel, AND A VIDEO, on our main website at [POPYACHTS DOT COM](http://POPYACHTS.DOT.COM). We appreciate that you took your time to look at our advertisement and we look forward to speaking with you!**

Condition

She appears to be in good condition. The photos tell the story. The paint is in good condition and there's no visible damage to any of the exterior.

The upholstery, carpet and gel coat are in good condition. The boat's been stored covered.

An inspection is recommended to verify the condition.

Navigational Equipment

- Perfect Pass

Mechanical

- Ballast Bags
- Bilge Pump
- Fuel Injected
- Rudder
- Throttle/shift: Mech

Electrical Systems

- Fuel Gauge
- Speedometer
- Stereo (Clarion)
- Hour Meter

Deck Gear

- Bimini
- Bow Seating
- Captain's Chair
- Cockpit Seating
- Compartment Storage
- Steering Wheel
- Windshield - Walk Through
- Carpet - Cockpit
- Cover - Full Boat
- Swim Platform
- Wakeboard Tower



Copyright 1992 - 2023 MarineSource Network, Inc. <https://marinesource.com>. All Rights Reserved.